

POWER LUBER PUMP ASSEMBLY ISSUES 1400 AND 1800

I've created the chart below to illustrate the kit changes as clearly as possible. Yes, the 286102 is replaced by the 286404 and yes it is versatile enough to be used in the older models of the 1400 as well as the newer models.

The 286112 has been replaced by two new kits; 286402 and 286403 ; Two kits were required because new handle assemblies are included. New handles are required to allow models built through 2011 to be repaired.

We've included the handles and new pressure relief valve at no cost. The new numbers fit all sizes past, present and foreseeable future.

Original Service Kits	Description	Replaced by NEW PowerLuber Service Kits	
286112	PUMP HOUSING, GEAR AND BEARING	286402	14.4v PUMP ASSEMBLY KIT
			PUMP HOUSING, GEAR AND BEARING
			14.4V LEFT AND RIGHT HANDLES AND FASTENERS
			RELIEF VALVE ASSEMBLY
286112	PUMP HOUSING, GEAR AND BEARING	286403	18v PUMP ASSEMBLY KIT
			PUMP HOUSING, GEAR AND BEARING
			18V LEFT AND RIGHT HANDLES AND FASTENERS
			RELIEF VALVE ASSEMBLY
286102	14.4V PUMP ASSEMBLY KIT WITH MOTOR	286404	14.4v PUMP ASSEMBLY KIT W/MOTOR
			14.4 PUMP ASSY KIT W/ MOTOR & RELIEF VALVE
			14.4V LEFT AND RIGHT HANDLES AND FASTENERS
286220	18V PUMP ASSEMBLY KIT WITH MOTOR	286405	18v PUMP ASSY KIT W/MOTOR
			18V PUMP ASSY KIT W/ MOTOR & RELIEF VALVE
			18V LEFT AND RIGHT HANDLES AND FASTENERS