

#### **Information on Gear Set Kit 260339**




Current Arrangement of the 260339. This item was changed by Lincoln in approximately the year 2018. It is currently missing part 261002 and part number 261218 Needle Bearing. If you need these parts in your power luber, order 271892 Gear Kit assembly for the Series B 1200 Power Luber.

# **Previous Arrangement for Gear Set Kit 260339**




Previous components in Gear Set Kit 260339. Please note: item 261002 is no longer included in Gear Set Kit 260339. The same with main ring bearing 261218. The item 261218 was a press fit into the block and most people never used it.

### Part 261002




Part 261002: Not included in current Gear Set kit 260339. Purchase Kit 271892 if you need this part Included.

#### Part Number 261218



261218; Needle Bearing or Main Bearing not included in the kit 260339. Purchase this part separately. However it is pressed into the block and you need to get the old one out before you press the new one in. It can be a trying to get the old one out without damaging the block.

## Bill of Materials for the kit 260339



List of all the parts in the New Gear Set kit 260339. Notice missing 261218 and 261002